

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402395187

Date Received:

05/11/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901585

Inspection Date: 03/24/2020

FIR Submit Date: 03/30/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325961

Location Name: ALLISON UNIT-N32N6W Number: 20SWNW County: LA PLATA

Qtrqr: SWN Sec: 20 Twp: 32N Range: 6W Meridian: N  
W

Latitude: 37.004250 Longitude: -107.529850

FACILITY - API Number: 05-067- -00 Facility ID: 215638

Facility Name: ALLISON UNIT Number: 116

Qtrqr: SWN Sec: 20 Twp: 32N Range: 6W Meridian: N  
W

Latitude: 37.004250 Longitude: -107.529850

CORRECTIVE ACTIONS:

1 ☒ CA# 137552

Corrective Action:

Date: \_\_\_\_\_

-Revegetation needs to be conducted throughout the majority of the project area. Revegetation needs to be monitored by qualified personnel, knowledgeable of revegetation, weeds, and stormwater, and managed as needed to ensure that revegetation is increasing. Documentation of monitoring may be requested. Livestock exclusion will likely be needed for successful revegetation.

-Remove unused equipment.

Response: CA COMPLETED

Date of Completion: 05/08/2020

Operator Comment: Revegetation has been completed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 137553

Corrective Action: Erosion controls (ie: mulch, blankets, etc.) and stormwater controls (ie: BMPs) are needed throughout the project area until the location is stabilized with desirable perennial vegetation.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 05/08/2020

Operator Comment: Erosion and stormwater controls have been established. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 5/11/2020 3:06:01 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402395187	FIR RESOLUTION SUBMITTED
402395190	Allison Unit 116_Resolved Photos

Total Attach: 2 Files