

Date 6-15-07  
 Service Number 07-32- 00052  
 Page 1 of 1  
 Time Arrive on Location 11:00  
 Time Depart Location 3:00  
 Miles from Nearest Field Office \_\_\_\_\_



Truck No. 47 Crane No. \_\_\_\_\_  
 Engineer Erickson Gun Loader (if necessary) \_\_\_\_\_  
 Operator Hlvorsen Operator \_\_\_\_\_  
 Operator Henderson Operator \_\_\_\_\_  
 Well to JW Wireline (Time): \_\_\_\_\_ Well to Customer (Time): \_\_\_\_\_  
 Total Operating Time \_\_\_\_\_ Total Standby Time \_\_\_\_\_ Total Lost Time \_\_\_\_\_

Company Renegade Gas & Oil Customer No. \_\_\_\_\_  
 Bill to (if other than above) \_\_\_\_\_ Purchase Order No. \_\_\_\_\_  
 Address \_\_\_\_\_ AFE / Contract No. \_\_\_\_\_  
 City, State Zip Code \_\_\_\_\_

Wellsite Information  
 Lease/Well Name Ferguson 5-25 Field Name \_\_\_\_\_  
 County/Parish \_\_\_\_\_ State Colorado Rig Name or Crane \_\_\_\_\_  
 Section / Township / Range or Latitude / Longitude X: \_\_\_\_\_ Y: \_\_\_\_\_ Perf Interval (See Below) \_\_\_\_\_  
 Log Measured From \_\_\_\_\_ Feet Above Permanent Data \_\_\_\_\_

Line Item #	DESCRIPTION	Quantity / Depth / Interval	Unit Price	Operation Charge	Line Total
1	Operation Charge				200 <sup>00</sup>
2					
3	Perforations 7164-7170(24)4SPF	1-10	Min.		900 <sup>00</sup>
4	7176-7182(24)4SPF	11-4/8	25 <sup>00</sup>		950 <sup>00</sup>
5	Barrel Charge		20 <sup>00</sup> ft.		240 <sup>00</sup>
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					

Surface Pressure \_\_\_\_\_ # Wireline Runs 1 Field Total: 2290<sup>00</sup>  
 Pressure Equip. Type: \_\_\_\_\_

Run No.	Interval Perforated / Plug Set	Type	SPF	# of Holes Shot	Run No.	Interval Perforated / Plug Set	Type	SPF	# of Holes Shot
1		Stick	4	4/8	9				
2					10				