

| Location | | | |
|--|--|-----------------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | in crop | | |
| Corrective Action | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | Date: |
| Corrective Action: | | | Date: |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Debris from dead weeds inside wellhead fencing. See attached photos. | | |
| Corrective Action: | Comply with Rule 603.f. | | Date: 09/27/2020 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Plunger Lift | # 1 | corrective date | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 247062 Type: WELL API Number: 123-14859 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action: Date:

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679601955. All previous corrective actions have been resolved. One new corrective action has been observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Thursday, August 27, 2020 at approximately 10:50, I, Inspector Brittani Santistevan, conducted an on-site inspection at GERRY 3 (PDC Energy), at location #: 327560 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. Debris from dead weeds inside wellhead fencing. Remove and comply with Rule 603.f. (Corrective Action Date: September 27, 2020) See attached photos #3,4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | santistb | 08/27/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 679603253 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233671 |