

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/28/2020

Document Number:

693503415**FIELD INSPECTION FORM**Loc ID 318149 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogccinspection@pdce.com	ALL INSPECTIONS
Lara-Mesa,	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240713	WELL	PR	10/01/2018	OW	123-08501	OUR DIANE 32-27	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate KPK has installed company sticker over PDC sign.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds on location and around equipment.		
Corrective Action:	Comply with rule 603f	Date:	11/27/2020
Type	OTHER		
Comment:	Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B	Date:	11/27/2020
Type	OTHER		
Comment:	Mechanical issue. Pumping unit motor appears to be leaking.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	11/27/2020
Type	OTHER		
Comment:	Stained soil around 55gal drum. around PU motor and exhaust pipe.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	11/27/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>240713</u>	Type: <u>WELL</u>	API Number: <u>123-08501</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>			
Corrective Action:		Date:	
Complaint			
Comment:		<p>Inspection in response to complaint. Field Inspector Assigned: Randy Silver Complaint Received Date: 8-26-2020 Complaint Contacted: Date: 8-27-2020 Time: 1:19PM via Phone Location ID # 318149,318641,318642 Location name: Our Diana #32-27, Rocky Mountain Fuel CO H #1, Rocky Mountain Fuel CO H #2 Inspection Document # 693503415, 693503417,693503419 Complaint Document # 200449156 Nature of Complaint: Maintenance and production Field Inspector Actions: On 8-26-2020, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to maintenance and production. On 8-27-2020, I attempted to make contact with the complainant contact Paula who stated concerns with non-production of wells and maintenance issues. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I observed several maintenance issues with the Our Dian and Rocky Mountain Fuel CO H#1. Corrective actions have been issued for observed maintenance issues. In regards to production, production, records submitted to the COGCC show production as of 6-20. These are all KP Kauffman wells. Weather conditions: Clear and location dry. All information reviewed and site inspection information were submitted to the COGCC for further review.</p>	
Corrective Action:		Date:	

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday August 27, 2020 at approximately 12:22PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Our Diane #32-27 Operator: KP Kauffman~ API#: 05-123-08501 County: Weld While there, I observed a producing well site. During this inspection the following possible compliance issues were observed: Debris: Rule 603 f Corrective action date of 11-27-20 See photos 1,2 Mechanical issue: Rule 605 d Corrective action date of 11-27-20 see photo 4 Stained soil: rule 907 A Corrective action date of 11-27-20 see Photos 2,3,4 Material handling: Rule 1002 f B Corrective action date of 11-27-20 See Photo 2 Weather conditions: Clear and location dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503416	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234757