



00818012

OGCC FORM 4

REV. 7-64

OIL AND GAS CONSERVATION COMMISSION **DEPARTMENT OF NATURAL RESOURCES** **OF THE STATE OF COLORADO**

File in duplicate for Patented and Federal lands.
 File in triplicate for State lands.

RECEIVED

JUL 17 1972

COLO. OIL & GAS CONSERV. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

The Bovaird Supply Company

3. ADDRESS OF OPERATOR

Box 609 Kimball, Nebraska 69145

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
 See also space 17 below.)
 At surface

At proposed prod. zone

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Parke

9. WELL NO.

1-A

10. FIELD AND POOL, OR WILDCAT

W. Padroni

11. SEC., T., R., M., OR BLK. AND
 SURVEY OR AREA

NE
 6-SW-SE Sec 1-9N-53W

12. COUNTY

Logan

13. STATE

Colorado

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☒

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL

CHANGE PLANS

(Other)

Plugging

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

REPAIRING WELL

☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT

(Other)

(NOTE: Report results of multiple completion on Well
 Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work Soon As Possible

T.D. 5088'

8-5/8" Surface Casing @ 105'--Cement to Surface

5-1/2" Casing @ 5080'

Perfs 4664__4668, 4685__4705, 5042__5069, 5069__5088

Dump Sand Across Perfs & 5 Sax Cement Plugg__9# Mud Between Plugs__
 15 Sax Across Surface CasingShoe__10 Sax at Top__Weld Plate On Top
 Of Surface.

Plug Water Sands If Necessary__Please Instruct.

DVR	
FJP	
HHM	
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>

18. I hereby certify that the foregoing is true and correct

J.A. "Pete" Peterson

Store Manager

May 19, 1972

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: