

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402494675

Date Received:
09/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902231
Inspection Date: 09/01/2020 FIR Submit Date: 09/04/2020 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326465

Location Name: DAVIS-N34N8W Number: 5SWNE County: LA PLATA
Qtrqtr: SWNE Sec: 5 Twp: 34N Range: 8W Meridian: N
Latitude: 37.246840 Longitude: -107.764510

FACILITY - API Number: 05-067-00 Facility ID: 216544

Facility Name: DAVIS Number: 2-5
Qtrqtr: SWNE Sec: 5 Twp: 34N Range: 8W Meridian: N
Latitude: 37.246840 Longitude: -107.764510

CORRECTIVE ACTIONS:

1 CA# 141698

Corrective Action: Long-term stormwater and erosion controls need to be installed to stabilize erosion and prevent sediment discharge from the project area. Stormwater velocities in diversions appear to be high and need to be reduced to prevent sediment loads being carried off site. Erosion controls need to be maintained on bare soils of the cut-slope until stabilized with desirable perennial vegetation. Sediment in roadside ditches and along the access road needs to be cleaned out. Stormwater and erosion controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 10/30/2020

Response: CA COMPLETED

Date of Completion: 09/21/2020

Operator
Comment:

Stormwater and erosion controls have been installed on the wellsite. See attached photos.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 9/22/2020 6:47:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402494676	Davis 2-5_Resolved Photos
-----------	---------------------------

Total Attach: 1 Files