

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402463052

Date Received:

08/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901414

Inspection Date: 02/10/2020

FIR Submit Date: 02/12/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333708

Location Name: STATE GAS COM CD-M34N7W Number: 17NWSW County: _____

Qtrqtr: NWS Sec: 17 Twp: 34N Range: 7W Meridian: M
W

Latitude: 37.188564 Longitude: -107.637411

FACILITY - API Number: 05-067- -00 Facility ID: 333708

Facility Name: STATE GAS COM CD-M34N7W Number: 17NWSW

Qtrqtr: NWS Sec: 17 Twp: 34N Range: 7W Meridian: M
W

Latitude: 37.188564 Longitude: -107.637411

CORRECTIVE ACTIONS:

1 ☒ CA# 136498

Corrective Action: Remove and properly store unused trailers.

Date: 03/15/2020

Response: CA COMPLETED

Date of Completion: 08/04/2020

Landowner has removed their personal trailer that was parked on location and has been informed of COGCC rules on storage on pad.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 136499

Corrective Action: Reclamation needs to be conducted in areas not needed for production operations in accordance with 1003 reclamation rules.

Date: 04/15/2020

Response: CA COMPLETED

Date of Completion: 08/04/2020

Operator
Comment: Outer perimeter of location was graded, seeded, mulched and crimped. Work area was minimal based off requirements for work over rig spacing. See attached

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 136500

Corrective Action: Stormwater controls need to be installed to stabilize erosion along the northeastern edge of the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 02/28/2020

Response: CA COMPLETED

Date of Completion: 08/04/2020

Operator
Comment: Erosion issues and BMP's maintained and addressed. Old wattles no longer needed removed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been completed see attached. Delay of work is due to needing landowner to remove trailer to complete all work which took time.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 8/10/2020 1:27:52 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402463052	FIR RESOLUTION SUBMITTED
402463071	Work completion photos

Total Attach: 2 Files