

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402494704

Date Received:

09/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902177

Inspection Date: 08/20/2020

FIR Submit Date: 08/24/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333506

Location Name: BONDAD 33-10-N33N10W Number: 1NENE County: LA PLATA  
Qtrqr: NENE Sec: 1 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.137560 Longitude: -107.880000

FACILITY - API Number: 05-067- -00 Facility ID: 258031

Facility Name: BONDAD 33-10 Number: 106  
Qtrqr: NENE Sec: 1 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.137560 Longitude: -107.880000

CORRECTIVE ACTIONS:

1 ☒ CA# 141438

Corrective Action: -Kochia debris needs to be removed and properly disposed of by 9/24/2020.

Date: 09/24/2020

Response: CA COMPLETED

Date of Completion: 09/18/2020

Operator Comment: Kochia debris removed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 141439

Corrective Action: -Unused equipment needs to be removed or returned to service by 9/24/2020.

Date: 09/24/2020

Response: CA COMPLETED

Date of Completion: 09/18/2020

Operator  
Comment: Unused equipment reinstalled

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 141440

Corrective Action: -Revegetation needs to be conducted within the project area by 11/1/2020. See "Stormwater" below for erosion control.

Date: 11/01/2020

Response: CA COMPLETED

Date of Completion: 09/18/2020

Operator  
Comment: location reseeded

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

4 ☒ CA# 141441

Corrective Action: Erosion controls such as mulch need to be installed and maintained in place until interim reclamation areas are stabilized with desirable perennial vegetation.

Date: 11/01/2020

Response: CA COMPLETED

Date of Completion: 09/18/2020

Operator  
Comment: Crew corrected erosion issues by cleaning out silt traps, re-establishing drainage around the location and reseeded

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker

Signed:

Title: Operation Regulatory Tech

Date: 9/22/2020 8:08:42 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402494704	FIR RESOLUTION SUBMITTED
402494725	BONDAD 33-10 106_Resolved Photos

Total Attach: 2 Files