

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402524605

Date Received:
11/03/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559

Name of Operator: SOUTHLAND ROYALTY COMPANY LLC

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Hampton, John

505-330-4377

jhampton@ctfieldsvcs.com

Blaylock, Connie

cblaylock@mspartners.com

Howe, Mike

MHowe@ctfieldsvcs.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902333

Inspection Date: 10/01/2020

FIR Submit Date: 10/06/2020

FIR Status: _____

Inspected Operator Information:

Company Name: SOUTHLAND ROYALTY COMPANY LLC

Company Number: 10559

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 334035

Location Name: QUINTANA 32-6-N32N6W Number: 15SWSE County: LA PLATA

Qtrqr: SWSE Sec: 15 Twp: 32N Range: 6W Meridian: N

Latitude: 37.011380 Longitude: -107.486180

FACILITY - API Number: 05-067- -00 Facility ID: 262

Facility Name: QUINTANA 32-6 Number: 15-4

Qtrqr: SWSE Sec: 15 Twp: 32N Range: 6W Meridian: N

Latitude: 37.011380 Longitude: -107.486180

CORRECTIVE ACTIONS:

1 CA# 142611

Corrective Action: Remove and properly dispose of waste and debris.

Date: 11/01/2020

Response: CA COMPLETED

Date of Completion: 11/03/2020

Operator
Comment:

Waste and debris have been removed and disposed of as of 11/3/20.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 142612

Corrective Action: Bare soils need to be stabilized with desirable vegetation. Seeding needs to be conducted by 11/1/2020. Weeds need to be controlled at the appropriate time and no later than 6/1/2021. Livestock exclusion may be needed to successfully establish desirable vegetation here.

Date: 11/01/2020

Response: CA COMPLETED

Date of Completion: 11/03/2020

Operator
Comment:

The area has been reseeded as of 11/3/20. Weeds will be sprayed at the appropriate time.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 142613

Corrective Action: Stormwater controls (ie BMPs) and erosion controls (ie hydromulch products, blankets, etc.) are needed to stabilize erosion within the project area. Stormwater and erosion controls need to be selected, sized, installed using good engineering practices, and maintained until stabilized with desirable perennial vegetation.

Date: 11/01/2020

Response: CA COMPLETED

Date of Completion: 11/03/2020

Operator
Comment:

Dirt has been moved and wattles reinstalled as of 11/3/20 to control stormwater and erosion.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been completed as of 11/3/2020. We were unable to complete them by 11/1 due to very muddy conditions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed: _____

Title: Regulatory Analyst

Date: 11/3/2020 1:45:52 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files