

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2020

Submitted Date:

11/10/2020

Document Number:

693503765**FIELD INSPECTION FORM**

Loc ID 318480 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Lara-Mesa,	303-825-4822	cogcc@kpk.com	All inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241373	WELL	PR	05/07/1977	OW	123-09162	MARVIN E. SCHUTT UNIT 1	PR

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Safety fence not closed and locked.		
Corrective Action:	All pumps, pits, and producing facilities shall be adequately fenced to prevent access by unauthorized persons when the producing site or equipment is easily accessible to the public and poses a physical or health hazard. Comply with rule 605 c (3)		Date: 11/10/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	Electric panel		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241373 Type: WELL API Number: 123-09162 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday November 10, 2020 at approximately 12:04PM, I, Inspector Randy Silver, conducted a on-site inspection due to a complaint Doc # 200449259</p> <p>Location: Marvin E Schutt Unit1</p> <p>Operator: KP Kauffman</p> <p>API: 123-09162</p> <p>County: Weld</p> <p>While there, I observed a well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Safety fence: 603 c 3</p> <p>Weather conditions: sunny and location wet due to snow.</p> <p>At time of inspection pumper was on site told him about gate and he closed gate.</p> <p>After an internal review of recent inspections at KPK facilities, COGCC Staff has determined that KPK has repeatedly and consistently failed to comply with certain COGCC rules (categorized in those inspection reports as violations related to "Signs/Marker," "Emergency Contact Number," and/or "Good Housekeeping"). In light of this apparent pattern of violations, violation(s) identified in this inspection report under those categories are being entered for notification and documentation only and are not intended to provide KPK the potential opportunity to resolve the alleged violation(s) without the imposition of penalty, pursuant to Rule 522.c. Therefore, in this inspection report, COGCC Staff has documented violation(s) and identified relevant corrective action(s) required to return to compliance, and pursuant to Rule 522.c., retains discretion to seek penalties for any violation documented in this inspection report.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	11/10/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503766	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289331">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289331</a>