

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402542394

Date Received:
11/30/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689805007
Inspection Date: 11/17/2020 FIR Submit Date: 11/20/2020 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324590

Location Name: DWINELL-610N79W Number: 23SESW County: _____
Qtrqr: SESW Sec: 23 Twp: 10N Range: 79W Meridian: 6
Latitude: 40.818090 Longitude: -106.233050

FACILITY - API Number: 05-057-00 Facility ID: 324590

Facility Name: DWINELL-610N79W Number: 23SESW
Qtrqr: SESW Sec: 23 Twp: 10N Range: 79W Meridian: 6
Latitude: 40.818090 Longitude: -106.233050

CORRECTIVE ACTIONS:

1 CA# 144528

Corrective Action: Inspector contacted KPK Max Knop at approximately 3:45 PM to inform him of the leak and the 24 hour window KPK had with which to repair it. Date: 11/18/2020

Response: CA COMPLETED Date of Completion: 11/18/2020

Operator Comment: KPK has repaired the tank leak.

COGCC Decision: _____

COGCC
Representative:

2 CA# 144529

Corrective Action: Properly dispose of oily waste in accordance with 907.e.
Comply with Rule 603.f .

Date: 11/09/2020

Response: CA COMPLETED

Date of Completion: 11/24/2020

Operator
Comment:

Stained soil behind tank battery has been removed. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

3 CA# 144530

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.

Date: 11/18/2020

Response: CA COMPLETED

Date of Completion: 11/20/2020

Operator
Comment:

The response was submitted on 11-20-2020: "There is no gas production from any of the Dwinell Battery's associated wells. Venting/flaring in not feasible at this location. If OGI recordings are observing any hydrocarbon emissions from the storage vessels it is a direct result of the flashing, working, or breathing losses that occur from normal oil production operations."

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Gen Manager of Gas Qualit

Date: 11/30/2020 2:11:52 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402542422	Completed CA PIC1
-----------	-------------------

Total Attach: 1 Files