

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2020

Submitted Date:

12/02/2020

Document Number:

700600225**FIELD INSPECTION FORM**
 Loc ID 321871 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 34105Name of Operator: GILBERT-STEWART OPERATING LLCAddress: 1801 BROADWAY STE 200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Axelson, John		john.axelson@state.co.us	
GILBERT, KENT	303-534-1686	kgoil@msn.com	
,	,	dnr_cogccenforcement@state.co.us	COGCC Enforcement
,	,	dnr_cogccengineering@state.co.us	COGCC Engineering

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208289	WELL	TA	01/01/2020	OW	017-07224	AKERS 2	EI

**General Comment:**

Noise from gas venting observed during inspection. RKL gas monitor detected methane gas venting. No Form 4 to approve venting/flaring found on file for well. Contacted operator at listed emergency number (303) 534-1686 at the time of inspection and again on 12/2/2020 but no there was no answer. Voicemails left instructing operator to contact COGCC EPS was not returned at the time this inspection was issued.

This is an environmental inspection only.

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Emergency contact number on lease sign is not monitored 24/7. No responses to voicemails left at the time of inspection were returned.Corrective Action: Install sign with emergency contact number that is monitored 24/7.

Date: 01/02/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	<span style="color: blue;">Gas being vented or flared during non-upset condition without prior approval from COGCC. See attached video. Operator informed immediately via phone call to cease venting.</span>		
Corrective Action:	<span style="color: red;">Immediately cease venting/flaring. Submit FIRR to inspector documenting corrective action.</span>	Date:	<u>12/02/2020</u>

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 208289 Type: WELL API Number: 017-07224 Status: TA Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600226	Gas monitor video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301291</a>
700600227	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301292">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301292</a>