

REV 12/6/2020

STRACHAN EXPLORATION
LINDA #2 (CLYDE FIELD)
NW/4 SEC 26-22S-45W
TROWERS CO
APC 05-099-06209

CASE 2

CAN NOT RECOVER PACKER.

8 3/4" 24" CMT TO SURF
1000-50 SX (5)
1000-50 SX

30" SURFACE PLUG
10 SX

10 SX 652-752'
10 SX 1000-1100'
1700-2000' (2)

4 1/2" 10.5"
DV TOOL @ 1794
CMT TOP UNKNOWN
NOTES 400 SX 50/50
PUMPED - CMT DID NOT
CIRCULATE

CMT TOP 2000'
2157' CASING REPAIRED
1496
3200' 500 PSI TEST
CIBP @ 3250'
2 SQZ @ 250 SX + 175 SX
FROM HONCO TIX

1250' (.0159) = 19.8 BBLS
111 ft³ / 1.18
95 SX

Plug 1 - CIBP @ 4500 10 SX*
4400-4500'

Plug 2 - 30 SX
1700-2000'

Plug 3 - 10 SX
1000-1100'

Plug 4 - 10 SX
752-652'

Plug 5 10 SX IF CMT FROM FO
483-383' SHOWS
NO CMT PERF @ 483'
50 SX 10 IN/40 OUT

Plug 6 10 SX SURFACE

TOC
4000'
CBL

MORROW PERFS
4620-24'

4937
PBTB

