

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402532567

Date Received:
12/12/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10421
Name of Operator: PETROLEUM RESOURCE MANAGEMENT CORP.
Address: 1580 LINCOLN ST., STE 635
City: DENVER State: CO Zip: 80203
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shepard, Duncan</u>	<u>303-861-9480</u>	<u>petromgt@att.net</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689804808
Inspection Date: 10/07/2020 FIR Submit Date: 10/14/2020 FIR Status: _____

Inspected Operator Information:

Company Name: PETROLEUM RESOURCE MANAGEMENT CORP. Company Number: 10421
Address: 1580 LINCOLN ST., STE 635
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 436485

Location Name: WPU-36 Number: 1 County: MOFFAT
Qtrqr: 19 Sec: 36 Twp: 11N Range: 89W Meridian: 6
Latitude: 40.860330 Longitude: -107.325016

FACILITY - API Number: 05-081-00 Facility ID: 436484

Facility Name: WPU-36 Number: 1V-H1
Qtrqr: 19 Sec: 36 Twp: 11N Range: 89W Meridian: 6
Latitude: 40.860330 Longitude: -107.325016

CORRECTIVE ACTIONS:

1 CA# 143953

Corrective Action: Install sign to comply with Rule 210.d. Date: 12/14/2020

Response: CA COMPLETED Date of Completion: 11/11/2020

Operator Comment: The wellhead sign was replaced. Please see the attached photograph for confirmation.

COGCC Decision: _____

COGCC
Representative:

2 CA# 143954

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 10/28/2020

Response: CA COMPLETED

Date of Completion: 11/11/2020

Operator Comment: The guy line anchor was painted a bright yellow and marked with red tape. Please see attached photograph for confirmation.

COGCC Decision:

COGCC
Representative:

3 CA# 143955

Corrective Action: Comply with Rule 603.f .
Properly dispose of oily waste in accordance with 907.e.

Date: 11/11/2020

Response: CA COMPLETED

Date of Completion: 11/11/2020

Operator Comment: The stained soils were removed. Please see the attached photograph.

COGCC Decision:

COGCC
Representative:

4 CA# 143956

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/14/2020

Response: CA COMPLETED

Date of Completion: 11/11/2020

Operator Comment: The missing tank label has been ordered however the sign company remains closed due to the Covid-19 pandemic, and they could not give us a date for their reopening. The tank label will be replaced as soon as the new label is received.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The pumper was unable to respond earlier to the corrective actions due to a death in his family. During his site visit on 11/11/20 he addressed three of the corrective actions and ordered a replacement label for the tank. The local internet fiber optic cable was down and have to be replaced delaying delivery of the attached CA photographs. An order was placed for the replacement tank label, however the sign company is temporarily closed due to the covid-19 pandemic, and no date has been set for their reopening. The label will be replaced as soon as we receive the new one.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rick Obernolte

Signed:

Title: Agent

Date: 12/12/2020 3:14:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402532573	Wellhead sign
402532578	Marked deadman
402532585	Stained soil removed

Total Attach: 3 Files