

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402552755

Date Received:

12/14/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902464

Inspection Date: 11/05/2020

FIR Submit Date: 11/06/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CONOCO PHILLIPS COMPANY

Company Number: 19160

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 385889

Location Name: ARGENTA 34-10-M34N10W Number: 31SENW County: LA PLATA

Qtrqr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M

Latitude: 37.147067 Longitude: -107.974791

FACILITY - API Number: 05-067-00 Facility ID: 89095

Facility Name: ARGENTA 34-10 Number: 31-1

Qtrqr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M

Latitude: 37.147067 Longitude: -107.974791

CORRECTIVE ACTIONS:

1 CA# 144228

Corrective Action: Control weeds at the appropriate time and no later than 6/1/2021.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 12/14/2020

Operator Comment: Weeds have been sprayed, see attached photos

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 144229

Corrective Action: -Additional stabilization is needed to stabilize disturbed soils and in the channel near the entrance to the former well pad, by 12/6/2020. This is a highly erosive area and permanent stormwater controls and erosion controls (seeding and mulching) need to be selected, sized, installed and maintained until long-term stabilization is achieved. Monitoring needs to be conducted.

Date: 12/06/2020

\*\*Care needs to be taken to avoid damaging and compacting vegetation when accessing location. Previous work resulted in vehicle tracking that could require additional reclamation.

Response: CA COMPLETED

Date of Completion: 12/04/2020

Operator Comment: Seeded and Mulched to stabilized disturbed soil near the well pad entrance. Seeded and mulched location access road due vehicle tracking disturbance.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker

Signed:

Title: Regulatory Operations Tech

Date: 12/14/2020 6:32:01 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402552756	Argenta 34-10-31-1 - Seeded/Mulched
402552757	Argenta 34-10-31-1 - Weeds Sprayed

Total Attach: 2 Files