

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402521647

Date Received:

10/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Michael Gardner

Phone

970-623-4875

Email

mgardner@terraep.com

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402358

Inspection Date: 06/30/2020

FIR Submit Date: 07/07/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 419862

Location Name: Mead Number: RWF 43-23 County: _____

Qtrqtr: NESE Sec: 23 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.510011 Longitude: -107.847131

FACILITY - API Number: 05-045-00 Facility ID: 419862

Facility Name: Mead Number: RWF 43-23

Qtrqtr: NESE Sec: 23 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.510011 Longitude: -107.847131

CORRECTIVE ACTIONS:

1 ☒ CA# 140294

Corrective Action: Remove Material pile that has become Debris.

Date: 11/16/2020

Response: CA COMPLETED

Date of Completion: 10/28/2020

Operator Comment: Debris has been removed. CA completed.

COGCC Decision: Approved

COGCC Representative: Site has been re-inspected.

2 ☒ CA# 140295

Corrective Action: There are two CAs in this section.
1) Control Noxious weeds ASAP
2) Reinstall Interim reclamation in Failing Interim Rec areas; conducting any activities necessary as indicated by Operator assessment by 11/16/20.

Date: 07/15/2020

Response: CA COMPLETED

Date of Completion: 10/28/2020

Operator Comment: 1) Noxious weeds have been removed / sprayed as appropriate.
2) Previously reclaimed areas deemed not successful have been reclaimed (again) per on-site meeting with TEP, COGCC (L. Colby), and land owner.
The CAs in this section have been completed.

COGCC Decision: Approved

COGCC Representative: Site has been re-inspected.

3 ☒ CA# 140296

Corrective Action: Install or repair required BMPs per Rule 1002.f.; Can be incorporated with Fall Reclamation Activities.

Date: 11/16/2020

Response: CA COMPLETED

Date of Completion: 10/28/2020

Operator Comment: BMPs have been repaired / installed to comply with Rule 1002.f and as discussed with COGCC (Lou Colby).
This CA has been completed.

COGCC Decision: Approved

COGCC Representative: Site has been re-inspected.

OPERATOR COMMENT AND SUBMITTAL

Comment: All CAs have been completed as discussed during on-site meeting with TEP, COGCC (L. Colby), and surface owner.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 10/29/2020 11:45:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

402521647	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files