



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Prime Mover

# 1

Comment: Electric motor

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: Electric

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 248356 Type: WELL API Number: 123-16154 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Annual Bradenhead test not current. Contact COGCC engineering

12/19/2020

Corrective Action: Comply with 341 c.

Date:

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <p><a href="#">COGCC Inspection Report Summary</a><br/>                     On 12/9/2020 at approximately 1335 I, Inspector Justin Medina conducted an on-site inspection at:<br/>                     Well Name- Rocky Mountain Fuel 21-8<br/>                     Company Name- KPK<br/>                     API- 05-123-16154<br/>                     In Weld County Colorado.<br/>                     While there, I observed producing well.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     Annual bradenhead test is not current. Contact COGCC engineering.<br/>                     Comply with 341 c. 12/19/20<br/>                     A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report.</p> | medinaj | 12/09/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402550173    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306792">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306792</a> |
| 699502007    | pics                 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306782">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306782</a> |