

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402492553

Date Received:
09/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Alyssa Beard</u>	<u>(303) 244-8114</u>	<u>abeard@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696302422
Inspection Date: 09/08/2020 FIR Submit Date: 09/08/2020 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 435380

Location Name: WICKSTROM Number: 6 CTB County: _____
Qtrqr: Lot 4 Sec: 6 Twp: 7N Range: 59W Meridian: 6
Latitude: 40.610860 Longitude: -104.025991

FACILITY - API Number: 05-123-00 Facility ID: 435380

Facility Name: WICKSTROM Number: 6 CTB
Qtrqr: Lot 4 Sec: 6 Twp: 7N Range: 59W Meridian: 6
Latitude: 40.610860 Longitude: -104.025991

CORRECTIVE ACTIONS:

1 CA# 141768

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 324 A.a

Date: 09/23/2020

Response: CA COMPLETED Date of Completion: 09/15/2020

Operator Comment: The day tank was not actually Foundation's, and we had it removed from the location. Tank removed shown in attached photo.

COGCC Decision: Approved

COGCC Representative: Approved

3 CA# 141770

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 09/23/2020

Response: CA COMPLETED

Date of Completion: 09/15/2020

Operator Comment: Stained soil at north tank loadlines was removed. Please see attached photo.

COGCC Decision: Approved

COGCC Representative: Approved

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: EHSR Manager

Date: 9/18/2020 9:18:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402492553	FIR RESOLUTION SUBMITTED
402492563	Stained soil removed
402492564	Day tank removed
402492565	Pit netting fixed - Wickstrom

Total Attach: 4 Files