

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2020

Submitted Date:

12/18/2020

Document Number:

700404643**FIELD INSPECTION FORM**Loc ID 314361 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228567	WELL	SI	11/01/2019	OW	103-05461	STINKING WATER 2W	SI

General Comment:

A routine inspection identified the following compliance issues:

- 1) Report past due for monthly operations. Complete by 7-15-2020.
- 2) Nearest public road missing on battery sign. Complete by 2-18-2021.

This is a summary of inspection report 700404643.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Nearest public road missing on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/18/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 228567 Type: WELL API Number: 103-05461 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations.Corrective Action: Submit required Form 7(s) to COGCC per rule 309.

Date: 07/15/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: None Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
3:20	PM	3:25	PM	Wellhead(s)

Comment: FLIR video acquired of well. No venting observed.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402557601	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5313771
700404644	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5313767
700404646	FLIR HSM video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5313768