

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2020

Submitted Date:

12/29/2020

Document Number:

688309283**FIELD INSPECTION FORM**Loc ID 317308 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 20275Name of Operator: CORAL PRODUCTION CORPAddress: 1600 STOUT ST STE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970) 768-5658	tcrumley@tcrumleypumpingse vice.com	
Young, Rob		rob.young@state.co.us	
Chonka, Jim	(303) 623-3573	jpchonka@netscape.net	
Wieger, Jim	(303) 623-3573	JIMWIEGER@QWESTOFFIC E.NET	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237995	WELL	PR	06/01/2020	OW	121-10498	LINDA 2	SI

General Comment:Spill Inspection

Pumper had previously called on 12/7/2020 to say that there was a spill at the tank battery. Vac truck was on location and have removed the free oil. Stained soil remained. Free oil observed under ice on first (north) produced water pit. REMOVE this free oil as soon as ice melts.

See inspection 688000503 and Form 19 #402548533/402548745 for COGCC EPS corrective actions that includes among other things to move tanks, collect samples, provide analytical results and disposal manifests, provide sketches, provide root cause and lessons learned.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Tank	>= 5 bbls		
Comment: Remove and properly dispose of stained soil inside tank berms.				
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.			Date: 12/25/2020	

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 237995 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	237995	Type:	WELL	API Number:	121-10498	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI for spill."/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: YESPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: HDPELiner Condition: AdequateComment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Metal GridNetting Condition: GoodComment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: YES2+ feet Freeboard: YESComment: Corrective Action: Date: Type: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>YES</u>	2+ feet Freeboard: <u>YES</u>
Comment:	Remove free oil as soon as ice melts (see attached photos).	
Corrective Action	Control and contain spills/releases and clean up per Rule 906.a.	
		Date: <u>12/30/2020</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402562287	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317750
688309284	Coral Production Linda 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317749