

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402499119

Date Received:  
09/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com
Middlebrook, Sonny	575-445-6724/575-445-8610	smiddlebrook@wapitienergy.com
Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103311

Inspection Date: 09/23/2020

FIR Submit Date: 09/23/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: 308210

Location Name: VPR C-635S66W Number: 15SENW County: LAS ANIMAS

Qtrqtr: SENW Sec: 15 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.000860 Longitude: -104.770180

FACILITY - API Number: 05-071-00 Facility ID: 264073

Facility Name: VPR C Number: 45

Qtrqtr: SENW Sec: 15 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.000860 Longitude: -104.770180

CORRECTIVE ACTIONS:

1  CA# 142278

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 10/23/2020

Response: CA COMPLETED

Date of Completion: 09/24/2020

The stain around the well head has been removed and cleaned-up. The soil was properly disposed of per rule.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 142279

Corrective Action: PLUMB BRADENHEAD TO USRFACE, COMPLY WITH RULE 608.e.

Date: 10/23/2020

Response: CA COMPLETED

Date of Completion: 09/24/2020

Operator  
Comment: Braden head has been plumbed to the surface.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3  CA# 142280

Corrective Action: REMOVE UNUSED EQUIPMENT, COMPLY WITH RULE 603.f.

Date: 10/23/2020

Response: CA COMPLETED

Date of Completion: 09/24/2020

Operator  
Comment: The wood that was on location has been removed .

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All of the corrective actions have been addressed and taken care of.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed: \_\_\_\_\_

Title: HSE Specialist

Date: 9/29/2020 8:35:14 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402499119	FIR RESOLUTION SUBMITTED
402499122	Bradenhead and Stain Cleaned-up
402499124	Area cleaned up
402499125	Trash removed

Total Attach: 4 Files