

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402552755

Date Received:
12/14/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902464
Inspection Date: 11/05/2020 FIR Submit Date: 11/06/2020 FIR Status: _____

Inspected Operator Information:

Company Name: CONOCO PHILLIPS COMPANY Company Number: 19160
Address: 925 N ELDRIDGE PARKWAY
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 385889

Location Name: ARGENTA 34-10-M34N10W Number: 31SENW County: LA PLATA
Qtrqr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M
Latitude: 37.147067 Longitude: -107.974791

FACILITY - API Number: 05-067- -00 Facility ID: 89095

Facility Name: ARGENTA 34-10 Number: 31-1
Qtrqr: SENW Sec: 31 Twp: 34N Range: 10W Meridian: M
Latitude: 37.147067 Longitude: -107.974791

CORRECTIVE ACTIONS:

1 ☒ CA# 144228

Corrective Action: Control weeds at the appropriate time and no later than 6/1/2021. Date: _____

Response: CA COMPLETED Date of Completion: 12/14/2020

Operator Comment: Weeds have been sprayed, see attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 144229

Corrective Action: -Additional stabilization is needed to stabilize disturbed soils and in the channel near the entrance to the former well pad, by 12/6/2020. This is a highly erosive area and permanent stormwater controls and erosion controls (seeding and mulching) need to be selected, sized, installed and maintained until long-term stabilization is achieved. Monitoring needs to be conducted.

Date: 12/06/2020

**Care needs to be taken to avoid damaging and compacting vegetation when accessing location. Previous work resulted in vehicle tracking that could require additional reclamation.

Response: CA COMPLETED

Date of Completion: 12/04/2020

Operator Comment: Seeded and Mulched to stabilized disturbed soil near the well pad entrance. Seeded and mulched location access road due vehicle tracking disturbance.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker

Signed:

Title: Regulatory Operations Tech

Date: 12/14/2020 6:32:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402552755	FIR RESOLUTION SUBMITTED
402552756	Argenta 34-10-31-1 - Seeded/Mulched
402552757	Argenta 34-10-31-1 - Weeds Sprayed

Total Attach: 3 Files