

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2021

Submitted Date:

01/26/2021

Document Number:

700702225

FIELD INSPECTION FORM

Loc ID 336014 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 950 17TH STREET, SUITE 1900
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278175	WELL	PR	12/20/2009	GW	045-10845	RIVER RANCH A4	PR
278176	WELL	PR	11/01/2020	GW	045-10846	RIVER RANCH A6	PR
278179	WELL	PR	01/15/2008	GW	045-10849	RIVER RANCH A1	PR
284272	WELL	PR	03/20/2012	GW	045-12124	RIVER RANCH A5	PR
284276	WELL	PR	12/20/2009	GW	045-12120	RIVER RANCH A3	PR

General Comment:

COGCC Inspection Report Summary
 On Tuesday 1/26/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa River Ranch A, at Location # 336014 in Garfield county Colorado.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. All C/A's from previous inspection document # 700701871 have been completed. Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.
 During this inspection the following possible compliance issues were observed:
 • Tank battery signage is missing information and located at entrance of location
 Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	snow covered		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	• Tank battery signage is missing information and located at entrance of location		
Corrective Action:	Comply with rule 605.e		Date: 04/26/2021
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 5		corrective date
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>278175</u>	Type:	<u>WELL</u>	API Number:	<u>045-10845</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>278176</u>	Type:	<u>WELL</u>	API Number:	<u>045-10846</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>278179</u>	Type:	<u>WELL</u>	API Number:	<u>045-10849</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>284272</u>	Type:	<u>WELL</u>	API Number:	<u>045-12124</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>284276</u>	Type:	<u>WELL</u>	API Number:	<u>045-12120</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				

Comment: [Limited storm water inspection due to snow cover Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702229	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337512