

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402402024

Date Received:

05/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10330

Name of Operator: INVESTMENT EQUIPMENT LLC

Address: 412 W PLATTE AVE

City: FT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Chisholm, Jim

Phone

405-642-9437

Email

investmentequipment@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688307817

Inspection Date: 05/07/2020

FIR Submit Date: 05/09/2020

FIR Status: _____

Inspected Operator Information:

Company Name: INVESTMENT EQUIPMENT LLC

Company Number: 10330

Address: 412 W PLATTE AVE

City: FT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 317137

Location Name: KINCHELOE-63S51W Number: 11SESW County: WASHINGTON

Qtrqr: SESW Sec: 11 Twp: 3S Range: 51W Meridian: 6

Latitude: 39.802739 Longitude: -103.061287

FACILITY - API Number: 05-121- -00 Facility ID: 236712

Facility Name: KINCHELOE Number: 1

Qtrqr: SESW Sec: 11 Twp: 3S Range: 51W Meridian: 6

Latitude: 39.802739 Longitude: -103.061287

CORRECTIVE ACTIONS:

1 ☒ CA# 138897

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/22/2020

Response: CA COMPLETED

Date of Completion: 05/18/2020

Operator Comment: Replaced leaking flow line valve.

COGCC Decision: Approved

COGCC
Representative:

2  CA# 138899

Corrective Action: Install BMP and/or discuss with landowner the bare areas left in the field from the 12/2019 spill.

Date: 05/22/2020

Response: CA COMPLETED

Date of Completion: 05/18/2020

Operator
Comment:

Landowner will just plow field after crops are out. All soil samples tested good.

COGCC Decision: **Not Approved**

COGCC
Representative:

See inspection #688309575 with photos of areas. Field not plowed yet however germination in spill areas was less than nonspill areas. Check crop growth in next growing season.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jim Chisholm

Signed:

Title: Manager / Member

Date: 5/19/2020 2:23:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|--------------------------|
| 402402024 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files