

TEP ROCKY MOUNTAIN LLC

UNOCAL-66S96W 34SENW

Location # 335366



**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Unmarked deadman on location.

TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366



Erosion rill from channel in perimeter berm.



Channel in perimeter berm.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Ditch needs maintained. Berm is poorly compacted.



Riling along berm running to access road.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Riling from location running along ditch on
access road.**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.47997 108.09347



Culvert basin needs maintained.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.47997 108.09347



Culvert and basin need maintained.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.48108 108.09493



Culvert basin and ditch need maintained.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.48108 108.09493



Culvert outlet basin needs maintained.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.48137 108.09501



Culvert basin needs maintained.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.48137 108.09501



Culvert flow creating erosion rill.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



Culvert 39.48137 108.09501



Culvert basin needs maintained.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-66S96W 34SENW
Location # 335366**



No evidence of tracking control BMP's



No evidence of tracking control BMP's