

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402604242

Date Received:

03/03/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: 106 GLENMOOR LN
City: ENGLEWOOD State: CO Zip: 80113

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
<u>Halde, Kerry</u>	<u>(719) 340-0329</u>	<u>haldeoil@hotmail.com</u>
<u>Shalberg, Greg</u>	<u>(719) 688-3547</u>	<u>gregshalberg@aol.com</u>
<u>Wiepking, Jeff</u>	<u>(303) 868-5061</u>	<u>jwiepking@msn.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Quint, Craig</u>		<u>craig.quint@state.co.us</u>
<u>Boone, Linda</u>	<u>(720) 271-8605</u>	<u>LDBoonePar@aol.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688309716
Inspection Date: 02/16/2021 FIR Submit Date: 02/16/2021 FIR Status: _____

Inspected Operator Information:

Company Name: WIEPKING-FULLERTON ENERGY LLC Company Number: 96340
Address: 106 GLENMOOR LN
City: ENGLEWOOD State: CO Zip: 80113

LOCATION - Location ID: 420531

Location Name: Napali Number: 2 County: LINCOLN
Qtrqtr: SESW Sec: 17 Twp: 10S Range: 55W Meridian: 6
Latitude: 39.173210 Longitude: -103.577600

FACILITY - API Number: 05-073-00 Facility ID: 420526

Facility Name: Napali Number: 2
Qtrqtr: SESW Sec: 17 Twp: 10S Range: 55W Meridian: 6
Latitude: 39.173210 Longitude: -103.577600

CORRECTIVE ACTIONS:

1 CA# 146636

Corrective Action: Per Rule 608e. Mechanical Conditions. All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. All equipment will be engineered, operated, and maintained within the manufacturer's recommended specifications.

Date: 03/18/2021

Response: CA COMPLETED

Date of Completion: 02/17/2021

Operator Comment: Napali 2 stuffing box leak was repaired.

COGCC Decision:

COGCC Representative:

2 CA# 146637

Corrective Action: Control and contain spills/releases and clean-up per Rule 912.

Date: 03/18/2021

Response: CA COMPLETED

Date of Completion: 02/26/2021

Operator Comment: Oily dirt from inside containment hauled to Waste Management in Bennett, CO.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Linda Boone

Signed:

Title: Agent

Date: 3/3/2021 10:42:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (http://ogccweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description

Total Attach: 0 Files