

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2021

Submitted Date:

03/15/2021

Document Number:

688800875

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
 Name of Operator: SIMCOE LLC
 Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900
 City: HOUSTON State: TX Zip: 77002

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		sjninspections@ikavenergy.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479418	SPILL OR RELEASE	AC	03/12/2021		-	JT Morris A1 Well Tie	EI

General Comment:

On March 12, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC JT Morris A #1 Well Tie Spill/Release Point ID #479418. For more information regarding this release, please refer to Spill/Release Report Document #402610834.

Location

Lease Road:			
Type	Main		
comment:	County Road 221 is adjacent to spill location.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Valve can approximately 200' west of Spill/Release Point reported by the operator.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Release was reportedly from an underground produced water transfer line. COGIS database indicates that a 3" polyethylene line, part of Facility ID #471426, is the point source.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 479418 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 32Comment: For more information regarding this Spill/Release, please refer to Document #402610834.Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. The operator shall submit any information that is available concerning failure analysis, integrity/pressure testing, and any data concerning the root causes of the spill. Provide all pipeline integrity data to the COGCC Western Integrity Inspector, Richard Murray, at (970) 989-3092 or g.richard.murray@state.co.us.Date: 04/15/2021Reportable: YESGPS: Lat 37.214849Long -107.787203

Proximity to Surface Water:

Depth to Ground Water: 40**Water Well Complaint:**

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
<p>On March 12, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC JT Morris A #1 Well Tie Spill/Release Point ID #479418. For more information regarding this release, please refer to Spill/Release Report Document #402610834.</p> <p>Release was reportedly from an underground produced water transfer line. COGIS database indicates that a 3" polyethylene line, a component of Facility ID #471426, is the point source.</p> <p>The release point had reportedly been repaired, samples collected, and the excavated area backfilled at the time of this inspection.</p> <p>The operator shall submit any information that is available concerning failure analysis, integrity/pressure testing, and any data concerning the root causes of the spill. Provide all pipeline integrity data to the COGCC Western Integrity Inspector, Richard Murray, at (970) 989-3092 or g.richard.murray@state.co.us.</p>	hughesjo	03/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800876	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5376816