

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/24/2021

Submitted Date:

03/24/2021

Document Number:

693504886

**FIELD INSPECTION FORM**
 Loc ID 330987 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Lara-Mesa,	303-825-4822	cogcc@kpk.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257529	WELL	PR	10/23/2000	OW	123-19990	ROCKY MOUNTAIN FUEL CO 15-9	PR

**General Comment:**

<b>Inspected Facilities</b>			
Facility ID: <u>257529</u>	Type: <u>WELL</u>	API Number: <u>123-19990</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <u>PR</u>			
Corrective Action:		Date:	
<b>Complaint</b>			
Comment:	<p>Inspection in response to complaint.  Field Inspector Assigned: Randy Silver  Complaint Received  Date: 3-15-2021  Complaint Contacted: yes via phone  Date: 3-24-2021 Time: 10:00AM  Location ID # 330987  Location name: Rocky Mountain Fuel CO 15-9  Inspection Document # 693504881  Complaint Document #200449460  Nature of Complaint: noise  Field Inspector Actions:  On 3-15-2021, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Lynn Johns 8690 County Road 10 stated the issues were occurring outside of complainants home.  On 3-23-2021, I attempted to make contact with the complainant who indicated that on 3-12-2021 experiencing a squealing sound from the pump unit to the north of complainants home. Noise usually occurs during nighttime hours.  I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, Pumping Unit was not running so I could not hear any noise. I spoke with KPK supervisor he stated he would look at timer and see if he can run it during day light hours and find source of noise. I time of inspection road was not assessable due to weather condition and no gravel on road. Inspector will be going out periodically to location to try to find source of noise.  No violation of COGCC rules were observed at the time of the inspection.  All information reviewed and site inspection information has been submitted to the COGCC for further review.</p>		
Corrective Action:		Date:	
<b>COGCC Comments</b>			
Comment	User	Date	
No violation of COGCC rules were observed at time of inspection in regards to complaint. All previous inspection corrective actions still apply.	silverr	03/24/2021	