

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402639677

Date Received:

03/25/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Michael Gardner

970-623-4875

COGCCInspectionReports@terraep.com

mgardner@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692403022

Inspection Date: 02/10/2021

FIR Submit Date: 02/15/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324102

Location Name: CLOUGH-66S94W Number: 20SWSW County: _____

Qtrqr: SWS Sec: 20 Twp: 6S Range: 94W Meridian: 6
W

Latitude: 39.504409 Longitude: -107.919621

FACILITY - API Number: 05-045- -00 Facility ID: 324102

Facility Name: CLOUGH-66S94W Number: 20SWSW

Qtrqr: SWS Sec: 20 Twp: 6S Range: 94W Meridian: 6
W

Latitude: 39.504409 Longitude: -107.919621

CORRECTIVE ACTIONS:

1 ☒ CA# 146646

Corrective Action: Control Noxious weeds.

Date: 05/01/2021

Response: CA COMPLETED

Date of Completion: 03/25/2021

Operator Comment: Site is part of routine weed maintenance program. Tamarisk growing along access road are originating from an uphill spring area (off location). TEP will remove any tamarisk that grow in the road and interfere with access to the location.

COGCC Decision: **Not Approved**

COGCC Representative: From wording of Comment, It appears Operator is disputing the necessity of controlling weeds growing along the access road, and will only control weeds growing in the access road. Access road footprint (road, area along road & ditches) is part of the disturbance in construction of this Location. Origin of weeds is not relevant to Control required. Tamarisk, a State B List Noxious weed is required to be controlled in compliance with the Colorado Noxious Weed Act and COGCC 1000 series rules.

2 ☒ CA# 146647

Corrective Action: Install, repair/maintain required BMPs per Rule 1002.f. by 4/1/21 or as soon as ground and weather conditions permit.

Date: 04/01/2021

Response: CA COMPLETED

Date of Completion: 03/25/2021

Operator Comment: BMPs have been repaired / maintained to comply with Rule 1002.f. Corrective action is complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed / completed. Site is ready for reinspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 3/25/2021 11:29:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402639677	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files