

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402610349

Date Received:

02/25/2021

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 4 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ferrin, Jeremy

jeremy.ferrin@state.co.us

MacLaren, Joe

joe.maclaren@state.co.us

.KPK

cogcc@kpk.com

Knop, Max

303-825-4822

MKnop@kpk.com

Canfield, Chris

chris.canfield@state.co.us

Axelson, John

john.axelson@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 691201383

Inspection Date: 02/22/2021

FIR Submit Date: 02/24/2021

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318201

Location Name: JAMES S HALEY TRUSTEE Number: 2SWSW County: _____
B-61N68W

Qtrqtr: SWS Sec: 2 Twp: 1N Range: 68W Meridian: 6
W

Latitude: 40.075100 Longitude: -104.976100

FACILITY - API Number: 05-123- -00 Facility ID: 478014

Facility Name: James S Haley Trustee B #2 Number: _____
Flowline

Qtrqtr: SWS Sec: 2 Twp: 1N Range: 68W Meridian: 6
W

Latitude: 40.075100 Longitude: -104.976100

CORRECTIVE ACTIONS:

Corrective Action: Report spill in accordance with Rule 912.b.(1).

Date: 02/25/2021

Response: FACTUAL REVIEW REQUESTBasis for Review: Action requested was already completed prior to the inspection

Operator Comment: Product observed at surface is associated with Spill/Release ID 478014, not a second subsurface release. A new spill/release at the same location has not occurred, as such will not be reported. Well and flowline associated with Spill/Release ID 478014 have been shut-in since initial release occurred. As noted in the inspection document, excavation activities have not been performed to remove released product from Spill/Release ID 478014. Until excavation activities are able to commence, there will be potential for additional product from Spill/Release ID 478014 to daylight; however, if this does occur, it will not be defined as an additional subsurface release.

COGCC Decision: **Not Approved**

COGCC Representative: Based on site visits and photographic evidence it is clear that hydrocarbon fluids continue to daylight to surface at this location.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Gen Mangr of Air QualityDate: 2/25/2021 10:25:07 AM**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402610349	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files