

HILL RANCH 07-09 API# 05-071-08065 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 31, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201284



PHOTO 1: THE ELECTRIC FENCE WAS REPAIRED.

HILL RANCH 07-09 API# 05-071-08065 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 31, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201284



PHOTO 2: THE BROKEN DOOR AND DOOR PARTS WERE REMOVED FROM THE SOUND WALLS.

HILL RANCH 07-09 API# 05-071-08065 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 31, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690201284



PHOTO 3: THE IMPACTED SOIL NEAR THE ENGINE SKID WAS REMOVED FROM LOCATION.