

APACHE CANYON 11-04 API# 05-071-06127 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 14, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103370




PHOTO 1: THE UNUSED EQUIPMENT WAS REMOVED FROM LOCATION.

APACHE CANYON 11-04 API# 05-071-06127 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER, 06 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103370



PHOTO 2: THE WELLHEAD PACKINGS WERE REPLACED AND THE STUFF BOX WAS SECURELY FASTENED TO STOP THE WATER LEAK. THE GROUND IS DRY AND NO IMPACTS WERE DISCOVERED.

APACHE CANYON 11-04 API# 05-071-06127 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 14, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103370



PHOTO 3: THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT OF THE LIQUID RING COMPRESSOR.

APACHE CANYON 11-04 API# 05-071-06127 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER, 21 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103370



PHOTO 4: THE SCRUBBER LIQUID WAS REMOVED FROM THE PRODUCED WATER TANK AND DISPOSED OF PER OGRIS'S WASTE MANAGEMENT PLAN AND THE COGCC RULES AND REGULATIONS.