

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402630043

Date Received:
03/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>		<u>spwu@chevron.com</u>
<u>sanford, anita</u>		<u>atlx@chevon.com</u>
<u>Olson, Andrew</u>		<u>andrewolson@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202348

Inspection Date: 02/19/2021 FIR Submit Date: 02/22/2021 FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 314804

Location Name: CARNEY C T-62N102W Number: 35NWNE County: _____

Qtrqtr: NWNE Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.106770 Longitude: -108.810490

FACILITY - API Number: 05-103-00 Facility ID: 314804

Facility Name: CARNEY C T-62N102W Number: 35NWNE

Qtrqtr: NWNE Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.106770 Longitude: -108.810490

CORRECTIVE ACTIONS:

1 CA# 146777

Corrective Action: Comply with Rule 606 and remove trash debris. Date: 03/22/2021

Response: CA COMPLETED Date of Completion: 03/16/2021

Operator Comment: Removed trash debris. Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 146778

Corrective Action: Comply with Rule 1002.f.(2)C and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition.

Date: 03/22/2021

Response: CA COMPLETED

Date of Completion: 03/16/2021

Operator Comment: Install required stormwater and erosion control BMPs. Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Completed. Please see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris patterson

Signed: _____

Title: Lead ENV Specialist

Date: 3/16/2021 11:07:47 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402630043	FIR RESOLUTION SUBMITTED
402630053	Photo
402630057	Photo

Total Attach: 3 Files