

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2021

Submitted Date:

04/21/2021

Document Number:

693700752**FIELD INSPECTION FORM**Loc ID 333156 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240989	WELL	PR	04/01/2019	OW	123-08777	JILLSON 'A' 1	EI
478617	SPILL OR RELEASE	AC	11/25/2020		-	Jillson 'A' #1	EI

General Comment:[COGCC Inspection of Spill ID 478617 and Jillson A 1 Tank Battery](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: At well and battery

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: Compressor building in desrepairCorrective Action: Repair building and remove debrisDate: 05/21/2021Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,

Comment: Open partially buried produced water vessel with netted top poses wildlife hazard. Repair net or replace tank.

Corrective Action: Repair net or replace tank.Date: 05/21/2021**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	240989	Type:	WELL	API Number:	123-08777	Status:	PR	Insp. Status:	EI
Facility ID:	478617	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: Spill was reported on 11/23/2020, field inspection 6910201395 on 2/23/2021 showed no indication of remedial excavation. This field inspection found no evidence of remedial excavation.

Corrective Action: Per Rule 912.a.(6).B Operator shall submit a Form 27 Workplan with a timeline for investigation and closure of this release. Operator shall also submit a Form 19-Supplemental requesting closure of this spill referencing the approved Remediation workplan.

Date: 02/21/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402667224	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409910
693700753	Jillson A1 Spill 478617 Photos 4-21-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409890
693700754	Jillson A Tank Battery Photos 4-21-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409891