

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2021

Submitted Date:

04/22/2021

Document Number:

688500309

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
CANFIELD, CHRIS 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Axelson, John		john.axelson@state.co.us	
Max Knop		mknop@kpk.com	

General Comment:

This is an environmental inspection of REM 16131. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contractor personnel on location at the time of this inspection.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: There is an open, partially flooded excavation which the operator has surrounded with steel barricade panels.No activity at the time of this inspection.

Corrective Action: Provide notice to COGCC at least 48-hours in advance to backfilling any open excavations related to REM 16131.

Date: 04/12/2021

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment

User

Date

This is an environmental inspection of REM 16131. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contractor personnel on location at the time of this inspection.

canfielc

04/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402668666	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411066