

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/23/2021

Submitted Date:

04/23/2021

Document Number:

699103438**FIELD INSPECTION FORM**
 Loc ID 441841 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Evins, Bret		bret.evins@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441839	WELL	PR	10/01/2016	OW	123-41533	70 Ranch State BB18-634	PR
441840	WELL	PR	10/01/2016	OW	123-41534	70 Ranch State BB18-655	PR
441841	LOCATION	AC			-	70 Ranch State BB18-655 Multi	AC
441842	WELL	PR	10/01/2016	OW	123-41535	70 Ranch State BB18-647	PR

General Comment:[New Compliance issues found on 4-23-21](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Oily waste from mechanical conditon, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	05/04/2021
Type	DEBRIS		
Comment:	Debris in multi locations, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	05/04/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	#		
Comment:	Balon/ tubing appear to be leaking need to be fixed or replaced.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 05/04/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 441839 Type: WELL API Number: 123-41533 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/30/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____End Surf Csg Pressure: 0Comment: Will need an updated annual bradenhead test on file after 4-30-21.

Corrective Action:

Date:

Facility ID: 441840 Type: WELL API Number: 123-41534 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/30/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Will need an updated annual bradenhead test on file after 4-30-21.

Corrective Action:

Date:

Facility ID: 441841 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing WellComment: AC

Corrective Action:

Date:

Facility ID: 441842 Type: WELL API Number: 123-41535 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/30/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____End Surf Csg Pressure: 0Comment: Will need an updated annual bradenhead test on file after 4-30-21.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 4/23/21 at approximately 0916hrs, I, Inspector Adam Burns, Conducted an on-site inspection at 70 Ranch State BB 18-655 Multi of Noble Energy, at Location ID # 441841 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Balon/ tubing appear to be leaking needs to be fixed or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 5/4/21.</p> <p>Oily waste underneath leaking mechanical conditions needs to be removed for good housekeeping. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/4/21</p> <p>Debris in multiple locations, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/4/21.</p> <p>All wells will need updated annual bradenhead test submitted after 4-30-21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402669239	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411515
699103439	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411503