

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402676428

Date Received:

04/30/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 11117 RIVER RUN BLVD

City: BAKERSFIELD State: CA Zip: 93311

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>John Hyder</u>	<u>435-722-1325</u>	<u>jhyder@bry.com</u>
<u>Andrea Gurr</u>	<u>435-722-1325</u>	<u>agurr@bry.com</u>
<u>Joseph Cobb</u>	<u>661-616-4234</u>	<u>jcobb@bry.com</u>
<u>Jon Armstrong</u>	<u>661-616-3941</u>	<u>jarmstrong@bry.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201998

Inspection Date: 11/02/2020

FIR Submit Date: 11/05/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BERRY PETROLEUM COMPANY LLC

Company Number: 10091

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

LOCATION - Location ID: 335964

Location Name: CHEVRON I31 596 Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqtr: NESE Sec: 31 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.568577 Longitude: -108.204330

FACILITY - API Number: 05-045-00 Facility ID: 335964

Facility Name: CHEVRON I31 596 Number: \_\_\_\_\_

Qtrqtr: NESE Sec: 31 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.568577 Longitude: -108.204330

CORRECTIVE ACTIONS:

1 CA# 144172

Corrective Action:

Date: \_\_\_\_\_

Due to seed dispersal being allowed and the onset of winter conditions resulting in plant dormancy, any weed management activities conducted will likely be insufficient until the 2021 growing season.

Therefore, no corrective action date is being provided in this inspection; this Location will remain out of compliance with Rule 1003.f until a followup inspection is conducted documenting that sufficient weed management activities have been performed to prevent the establishment and spread of noxious weeds:

Comply with Rule 1003.f. Ongoing noxious weed management/monitoring is required until Location receives a passing final reclamation inspection.

Response: CA COMPLETED

Date of Completion: 04/23/2021

Operator Comment: "All thistle were cut and bagged. Seed thatch from under plants was also bagged. We made sure to get as many seed heads as possible. Heavily infestation areas were sprayed with Milestone to take care of any rosettes and emerging rosettes. There were several second year Houndstounge that we also bagged up." ( Photos in attachments.)

For continuing weed management Berry plans to have the site visited at least 3 times by noxious weed management professionals with inspections planned to generally fall in mid-May, the end of June, August, and possible late September for assessment and any necessary treatment activities. While on site the personnel will walk the reclaim area in a tight grid pattern to assure every plant that is emerged is sprayed. Milestone herbicide will be used to ensure best results. Pictures will be taken during each visit to show current status and the results of ongoing treatment activities.

COGCC Decision:

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: See corrective action response.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Andrea Gurr

Signed:

Title: Regulatory Specialist 2

Date: 4/30/2021 11:44:51 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402676435	pic 6
402676436	pic 7
402676437	pic1
402676438	pic 2
402676439	pic 3
402676440	pic 4
402676442	pic 5

Total Attach: 7 Files