

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/11/2021

Document Number:

689805751**FIELD INSPECTION FORM**Loc ID 312756 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10386Name of Operator: POC-I LLCAddress: P.O. BOX 51208City: CASPER State: WY Zip: 82605**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Choury, Mark J.	303-818-0341	mchoury@prellc.com	
Tonnensen, John J.	303-518-3233	jtonnensen@prellc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222181	WELL	SI	07/01/2017	OW	081-05119	ILES DOME UNIT 8	SI

General Comment:

Routine FIU inspection. Compliance issues observed:
 stained soil
 no bradenhead access apparent
 expired Form 6 document number 402279880

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	307-237-7854 877-276-3556		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil on location.		
Corrective Action:	Comply with Rule 606. Properly dispose of oily waste in accordance with 905.e.		Date: 06/11/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	#		
Comment:	No bradenhead access apparent.		
Corrective Action:	Install bradenhead access and/or means of monitoring bradenhead pressure.		Date: 06/11/2021

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 222181 Type: WELL API Number: 081-05119 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

Well is overdue for Mechanical Integrity Test.
MIT requires 10-day notification via Form 42.
Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action:

Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 06/11/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689805767	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426254