

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2021

Submitted Date:

05/05/2021

Document Number:

689501240

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Brown, Kari _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		mknop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Axelson, John		john.axelson@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479713	SPILL OR RELEASE	AC	04/12/2021		-	Camenisch 1 sx Flowline Release	EI

General Comment:

This is a follow-up inspection to Doc # 689501195; environmental inspection of Spill ID 479713. Inspection of spill area only; adjacent facilities not inspected. No changes have occurred at the site since the previous inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash observed on location		
Corrective Action:	Comply with Rule 606		Date: 04/26/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Open excavation is fenced		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Spill excavation is open (approx. size 28'x20'x12'). Flowline appears to be repaired but impacts remain in situ. Sidewalls have begun to collapse into excavation. No groundwater was observed in the open excavation. Form 19 (Doc #402644033) lists spill discovery date as 3/29/2021.

Corrective Action: As Per Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered, Operator will submit Form 19 Supplemental requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate closure or a Form 27 Workplan with a timeline for investigation and closure of this release. If Remediation will continue under an approved Form 27, also submit a Form 19 Supplemental requesting closure of this spill referencing the approved Remediation workplan. Operator will provide notice to COGCC EPS Kari Brown (kari.l.brown@state.co.us) at least 48 hours prior to backfill or any sampling events performed on location. Note that samples collected must be analyzed for Table 915-1 parameters.

Date: 06/27/2021

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS: _____

Lat _____

Long _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment		Approx 5 cu yd of impacted material remain stored on location. Lining present in soil stockpile area does not adequately cover area of soil storage		
Corrective Action		Manage waste in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.		Date: 04/26/2021

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402681022	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421733
689501241	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421710