

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2021

Submitted Date:

05/05/2021

Document Number:

691201486

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465402	SPILL OR RELEASE	AC	01/28/2021		-	John Weigandt Consolidation	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.
There were no operator or contract environmental personnel on location at the time of this field inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	Trash in excavation and on location.		
Corrective Action:	Comply with Rule 606		Date: 05/11/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Inadequate fencing type and construction for livestock in area.		
Corrective Action:	Install fencing capable of controlling livestock around the entire perimeter of the excavation.		Date: 05/03/2021

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: **Spill remains open with no Form 27 Remediation workplan submitted (note: a Form 27 was submitted for separate Spill ID 472963). If Remediation will continue under an approved Form 27, also submit a Form 19 Supplemental requesting closure of this spill referencing the approved Remediation workplan.**

Corrective Action: **Operator must submit a Form 27 for COGCC review & approval. The requirement to submit a Form 27 was first communicated to the operator as a Corrective Action (due by 11/20/2020) in Field Inspection #689501111 and reiterated as a Condition of Approval (again with a deadline of 11/20/2020) applied to Form 19 Supplemental Report #402512650.**

Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Inadequate		
Comment	Hydrocarbon impacted soil remains in situ.			
Corrective Action	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.			Date: 01/15/2021
Oily Soil	Piles	Adequate		
Comment	Oily soils previously stockpiled have been removed.			
Corrective Action	Submit waste manifests via a supplemental Form 19.			Date: 05/14/2021

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402681024	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421735
691201487	Fencing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421712
691201488	Trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421713
691201489	Water in Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421714
691201490	Impacted Soils in Situ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421715