



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment: Following PA of this Orphaned Well, stained soil excavated around the wellhead was hauled off and replaced with clean fill.				
Corrective Action: Approximately 20 cubic yards of soil was removed from the Rosener #1 wellhead on May 19, 2021. The soil from the 10'x10'x8'deep excavation was transported to Buffalo Ridge in Keenesburg, CO for disposal. Groundwater was not encountered.				Date: <u>05/19/2021</u>

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
Preliminary results of on site screening by Fremont Environmental using a Photo Ion Detector showed no remaining soil that did not meet the required criteria. Confirmation samples were taken and results will be used to close the Form 19.	hickeymi	05/19/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402694832	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434103</a>
694200037	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434084</a>
694200038	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434085">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434085</a>