

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/20/2021

Submitted Date:

05/20/2021

Document Number:

699303866

FIELD INSPECTION FORM
 Loc ID 318072 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 70385

Name of Operator: SMITH ENERGY CORP

Address: 12706 SHILOH RD

City: GREELEY State: CO Zip: 80631

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240554	WELL	SI	09/01/2018	OW	123-08342	CUYKENDALL 12	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead inaccessible or not visible		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	05/30/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240554 Type: WELL API Number: 123-08342 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Bradenhead inaccessible or not visible

05/30/2021

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 5/20/2021 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Smith Energy Corp. location:</p> <p style="text-align: right;">Cuykedall 12 at API #05-123-08342 in Weld County Colorado.</p> <p>While there, I observed a wellsite. SI at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>419.a.(1), (2) Bradenhead Access: Bradenhead inaccessible or not visible CA date 5-30-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	05/20/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402696869	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5435580
699303867	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5435574