

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2021

Submitted Date:

06/04/2021

Document Number:

695104384**FIELD INSPECTION FORM**Loc ID 308721 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279627	WELL	PR	07/12/2007	GW	071-08510	SCHWEITZER 22-30	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: **TELEMETRY EQUIPMENT**

Corrective Action:

Date:

Type: Compressor

1

Comment: **WELL IS NOT UNDER PARTIAL VACUUM AT TIME OF INSPECTION.
COMPRESSOR SURROUNDED BY SOUND WALLS**

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: **IS PLUMBED TO SURFACE**

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: **CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE
LAST YEAR.**

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 279627	Type: WELL	API Number: 071-08510	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: **PHOTO 3: THERE IS MINOR VEHICLE TRACKING OBSERVED AT INTERSECTION.**

Corrective Action: **Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. Additionally, if material is tracked onto county or public roads, contact the appropriate authority.**

Date: 05/28/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	287550	1396275	

COGCC Comments

Comment	User	Date
<p>Inspection in response to complaint. Field Inspector Assigned: Tom Beardslee, Complaint Received Date: 5-24-21 Complaint Contacted: NO. Date: 5-24-21 Time: 3:18 PM via phone. Left voice mail. Did not receive a call back from complainant. Location ID # 308721, 333380, 334118 AND 334166 Location name: SCHWEITZER 22-30, MACGREGOR 34-25, GLORIA 42-25 AND SPYGLASS 13-30 TR. Inspection Document # 695104384 Complaint Document # 200449728 Nature of Complaint: VEHICLE TRACKING Field Inspector Actions: On 5-27-21, I Tom Beardslee area field inspector was assigned a complaint received by COGCC staff in reference to vehicle tracking on Wilderness Ridge Rd (a San Pablo POA), the complainant Dwayne Kent 16000 WILDERNESS RIDGE RD, Weston CO. 81091 stated that there is a tracking issue at a 5 way intersection of the Wilderness Ridge Road and the access roads to several oil and gas locations (locations listed above). Mr. Kent stated that heavy truck traffic and lack of road base and gravel the intersection has become muddy. I performed a complete site inspection of the oil and gas intersection listed in the complaint. At time of inspection, I found there is road base on the Wilderness Ridge Road. I also found a lack of road base on the joining oil and gas ROW'S. I spoke with David Baca with Evergreen about the issue and he told me he would have a contractor fix the issues. David call me back in app. 10 minutes and told me a contractor was on his way with a blade and a load of gravel to address the problem. (Insp. Doc# listed above). Note: At time of inspection, weather was warm. Intersection and ROW was dry. Weather conditions: partly cloudy, dry roads, 69*. All information reviewed and site inspection information submitted to the COGCC for further review.</p>	beardslt	05/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104385	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5447404