

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402010343

Date Received:
05/09/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Susana Lara-Mesa</u>	<u>303-825-4822</u>	<u>slaramesa@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685100772
Inspection Date: 04/10/2019 FIR Submit Date: 04/10/2019 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 322725

Location Name: CONNER-62N66W Number: 34NENW County: WELD
Qtrqtr: NENW Sec: 34 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.099310 Longitude: -104.766670

FACILITY - API Number: 05-123-00 Facility ID: 244145

Facility Name: CONNER Number: 21-34
Qtrqtr: NENW Sec: 34 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.099310 Longitude: -104.766670

CORRECTIVE ACTIONS:

1 CA# 124087

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/10/2019

Response: CA COMPLETED Date of Completion: 05/10/2019

Operator Comment: Stained soil in separator house has been removed. Please see attached picture.

COGCC Decision: Approved

COGCC
Representative:

2 CA# 124088

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.

Date: 05/07/2018

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment:

Stained soil under pump jack has been removed. Please see attached picture.

COGCC Decision: Approved

COGCC
Representative:

3 CA# 124089

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil

Date: 05/17/2018

Response: CA COMPLETED

Date of Completion: 05/09/2019

Operator
Comment:

Stained soil at the base of wellhead has been removed. Please see attached pictures.

COGCC Decision: Approved

COGCC
Representative:

4 CA# 124090

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/10/2019

Response: CA COMPLETED

Date of Completion: 05/09/2019

Operator
Comment:

The leak on tank has been fixed. Please see attached picture.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed: _____

Title: VP of Engineering

Date: 5/9/2019 1:53:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402010343	FIR RESOLUTION SUBMITTED
402038415	CA PIC1
402038418	CA PIC2
402038420	CA PIC3
402038426	CA PIC4
402038433	CA PIC5
402038442	CA PIC6

Total Attach: 7 Files