

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402668876

Date Received:

04/23/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10503
Name of Operator: RED HAWK PETROLEUM LLC
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kraich, Adam</u>		<u>adam.kraich@state.co.us</u>
<u>Boyd, William</u>		<u>wboyd@pedevco.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696303126
Inspection Date: 04/12/2021 FIR Submit Date: 04/12/2021 FIR Status: _____

Inspected Operator Information:

Company Name: RED HAWK PETROLEUM LLC Company Number: 10503
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 427041

Location Name: Buchner Number: 1-2H County: WELD
Qtrqtr: Lot 1 Sec: 2 Twp: 7N Range: 60W Meridian: 6
Latitude: 40.610890 Longitude: -104.052294

FACILITY - API Number: 05-123-00 Facility ID: 427019

Facility Name: Buchner Number: 1-2H
Qtrqtr: Lot 1 Sec: 2 Twp: 7N Range: 60W Meridian: 6
Latitude: 40.610890 Longitude: -104.052294

CORRECTIVE ACTIONS:

1 CA# 148300

Corrective Action: Install sign to comply with Rule 605.h. Date: 05/14/2021

Response: CA COMPLETED Date of Completion: 04/21/2021

Operator Comment: Sign updated with current contact information.

COGCC Decision: Approved

COGCC Representative: Approved

2 CA# 148301

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Cleanup Soil around Pumpjack per Rule 608.e.

Date: 02/06/2021

Response: CA COMPLETED Date of Completion: 04/21/2021

Operator Comment: Stained soil removed and properly disposed of.

COGCC Decision: Approved

COGCC Representative: Approved

3 CA# 148302

Corrective Action: Install sign to comply with Rule 605.d.

Date: 05/14/2021

Response: CA COMPLETED Date of Completion: 04/21/2021

Operator Comment: Signage restored from fading condition.

COGCC Decision: **Not Approved**

COGCC Representative: Middle Crude Oil Tank STILL has faded Labels. See FIR 696303349 dated 06.14.2021

4 CA# 148303

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Cleanup Soil around Pumpjack per Rule 608.e.

Date: 02/06/2021

Response: CA COMPLETED Date of Completion: 04/21/2021

Operator Comment: Stained soil removed and properly disposed of.

COGCC Decision: Approved

COGCC Representative: Approved

OPERATOR COMMENT AND SUBMITTAL

Comment: Photographs attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: William Boyd

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402668876	FIR RESOLUTION SUBMITTED
402668878	Photographs

Total Attach: 2 Files