

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402726587

Date Received:

06/22/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202702

Inspection Date: 05/14/2021

FIR Submit Date: 05/19/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335961

Location Name: CHEVRON Number: TR 11-1-698 County: \_\_\_\_\_

Qtrqr: NWS Sec: 1 Twp: 6S Range: 98W Meridian: 6  
W

Latitude: 39.561495 Longitude: -108.285197

FACILITY - API Number: 05-045- -00 Facility ID: 335961

Facility Name: CHEVRON Number: TR 11-1-698

Qtrqr: NWS Sec: 1 Twp: 6S Range: 98W Meridian: 6  
W

Latitude: 39.561495 Longitude: -108.285197

CORRECTIVE ACTIONS:

1 CA# 151148

Corrective Action: Comply with Rule 406.e.(4) and plug and reclaim conductors. Comply with Rule 1003 and perform interim reclamation of the Location. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. A CA date of 5/10/2021 is being provided as this was when interim reclamation was required by, per Sundry #402135498 conditions.

Date: 05/10/2021

Response: CA COMPLETED

Date of Completion: 06/08/2021

All conductors have been physically closed per Rule 406.e.(4) Additionally, Form 4s have been submitted to close the conductors and abandon the expired drilling permits for the Chevron TR 11-1-698 well pad. Interim

Operator  
Comment: reclamation of the location has been completed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This Corrective Action has been completed. Per the requirements of Rule 406.e.(4), all conductors have been closed and Form 4s have been submitted to abandon the expired drilling permits for this location. Interim reclamation of the location has been completed. The site is ready for reinspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental

Date: 6/22/2021 3:31:45 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files