

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402706411

Date Received:
06/02/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Christina Pierce

970-263-3626

cpierce@Laramie-Energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202120

Inspection Date: 12/08/2020

FIR Submit Date: 12/11/2020

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335815

Location Name: Cascade Creek Number: 697-08-53 County: _____

Qtrqr: NWSE Sec: 8 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.533992 Longitude: -108.241792

FACILITY - API Number: 05-045- -00 Facility ID: 335815

Facility Name: Cascade Creek Number: 697-08-53

Qtrqr: NWSE Sec: 8 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.533992 Longitude: -108.241792

CORRECTIVE ACTIONS:

3  CA# 145157

Corrective Action: Comply with Rule 1002.f.(2) and install BMPs in accordance with good engineering practices. Temporary controls will be required by 1/11/2021 until interim reclamation of the Location is conducted, at which point long-term controls will need to be implemented.

Date: 01/11/2021

Response: CA COMPLETED

Date of Completion: 05/27/2021

Operator Comment: issue addressed see attached reports

COGCC Decision: **Not Approved**

COGCC Representative: Followup inspection #696202855 on 6/23/2021 documented that Operator has implented temporary control measures to manage runoff (wattles); however, per the corrective action, control measures to protect/stabilize the cut and fill slopes of the Location remain missing or insufficient/inadequate.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed:

Title: Engineering Tech

Date: 6/2/2021 11:47:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402706411	FIR RESOLUTION SUBMITTED
402706415	corrective acton

Total Attach: 2 Files