

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402719901

Date Received:
06/18/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
_"		COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202818
Inspection Date: 06/10/2021 FIR Submit Date: 06/14/2021 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335145

Location Name: BARRETT-66S96W Number: 36NESW County: _____
Qtrqtr: NESW Sec: 36 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.478994 Longitude: -108.060605

FACILITY - API Number: 05-045-00 Facility ID: 335145

Facility Name: BARRETT-66S96W Number: 36NESW
Qtrqtr: NESW Sec: 36 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.478994 Longitude: -108.060605

CORRECTIVE ACTIONS:

1 CA# 151880

Corrective Action: Comply with Rule 1002.f.(2)C; Install or repair required Stormwater and Erosion control BMPs. Ensure control measures on the Location are adequate for the site's conditions, installed in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 04/13/2021

Response: CA COMPLETED Date of Completion: 06/15/2021

Operator Comment: Site is in compliance with Rule 1002.f.(2)C. BMPs have been installed or repaired.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: CAs have been completed. Site is ready for re-inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 6/18/2021 9:20:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402719901	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files