

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2021

Submitted Date:

06/09/2021

Document Number:

689805892

FIELD INSPECTION FORM

Loc ID 316758 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 6720
 Name of Operator: ROBERT L BAYLESS PRODUCER LLC
 Address: 621 17TH ST STE 2300
 City: DENVER State: CO Zip: 80293

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232649	WELL	SI	11/01/2020	GW	107-06063	DRY CREEK UNIT 3-22	PR

General Comment:

Routine FIU inspection. Compliance issues observed:
 stained soil on location
 unused equipment/debris on location
 previous pumper contact number in numerous places on location as emergency contact number, no clear number for operator emergency contact

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	NFPA labels becoming sun faded.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 505-327-0880 this number for operator is only listed at bottom of wellhead sign. Emergency contact stickes with previous pumper's number in numerous other places on location.

Corrective Action: Remove innaccurate emergency contact numbers.

Date: 07/09/2021

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead.		
Corrective Action:	Comply with Rule 606. Properly dispose of oily waste in accordance with 905.e.	Date:	06/23/2021
Type	STORAGE OF SUPL		
Comment:	Tubing stored on location.		
Corrective Action:	Comply with Rule 606.	Date:	07/09/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	#	
Comment:	No bradenhead access apparent.	
Corrective Action:	Install bradenhead access and/or means of monitoring bradenhead pressure.	Date: 07/09/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232649 Type: WELL API Number: 107-06063 Status: SI Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402725100	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5460323
689805893	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5460320