

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2021

Submitted Date:

07/12/2021

Document Number:

679604025**FIELD INSPECTION FORM**Loc ID 422949 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76840Name of Operator: SCHNEIDER ENERGY SERVICES INCAddress: P O BOX 889City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bothwell, Kevin	(970) 867-9437	kbothwell@rivalservices.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421458	WELL	TA	03/23/2019	OW	123-32924	WATTENBERG DRILLING FUND LLP 3	SI
421461	WELL	TA	03/23/2019	OW	123-32927	WATTENBERG DRILLING FUND LLP 4	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment behind tank battery. See attached photo		
Corrective Action:	Comply with Rule 606	Date:	10/12/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 421458 Type: WELL API Number: 123-32924 Status: TA Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SICorrective Action: Date: Facility ID: 421461 Type: WELL API Number: 123-32927 Status: TA Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: siCorrective Action: Date: **COGCC Comments**

Comment

COGCC Inspection Report Summary****Weather Conditions: sunny, dry ground**

On Monday, July 12, 2021 at approximately 14:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at EATON FIELD 2 (Schneider Energy Services), at location #: 422949 in WELD COUNTY Colorado.

While there, I observed a shut in facility.

During this inspection the following possible compliance issues were observed:

1. It appears to be unused equipment behind crude oil tanks inside berm. (Corrective Action Date: October 12, 2021) See attached photo #6.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

User

santistb

Date

07/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604026	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5476918